



Smart Focus 130/200/300/400

CNC-control



- 1) remove jumper in case of CNC operation
- 2) 1 V ≙ 50 A (galvanic isolated)
- 3) 1 V ≙ 25 V (galvanic isolated)

			drawn	date	name	designation CNC-interface Smart Focus 130/200/300/400 X102/X104/X106/X132/X4.1		
			appr.	02.10.14	RZA			
			norm					
exchange	02.10.15	RZA					draft-no.	sheet
exchange	15.06.15	RZA				.11.037.30xx..SP2 a	sh.1/1	
exchange	27.05.15	RZA						
change	date	name		repl.	be repl.			